

STATUS OF CLEANUP ACTIVITIES:

Cleanup activities are being conducted for source materials, soil, and groundwater.

CLEANUP PRIORITY: The Director has designated this site as a Class V

GA EPD DIRECTOR'S DETERMINATION REGARDING CORRECTIVE ACTION:

The Director has determined that this site requires corrective action.

REGULATED SUBSTANCES RELEASED, AND THREATS TO HUMAN HEALTH AND ENVIRONMENT POSED BY THE RELEASE:

This site has a known release of Benzo(a)pyrene in groundwater at levels exceeding the reportable quantity. No human exposure via drinking water is suspected from this release. The nearest drinking water well is between 1 and 2 miles from the area affected by the release.

REGULATED SUBSTANCES:

	2,4-Dimethylphenol 2-Chlorophenol Acenaphthene	> >	
	Acenaphthene		
	•	\checkmark	
			\checkmark
	Acetone	\checkmark	\checkmark
\checkmark	Arsenic	\checkmark	
	Benzene	\checkmark	\checkmark
\checkmark	Benzo(a)pyrene	\checkmark	\checkmark
\checkmark	Benzo(ghi)perylene		\checkmark
\checkmark	Beryllium	✓	
	Carbon disulfide	✓	\checkmark
	Chromium	\checkmark	
\checkmark	Copper	\checkmark	
\checkmark	Dichloromethane	\checkmark	\checkmark
	Ethylbenzene	\checkmark	\checkmark
\checkmark	Fluorene	\checkmark	\checkmark
	Heptachlor epoxide	\checkmark	
\checkmark	Lead	\checkmark	\checkmark
	Naphthalene	\checkmark	\checkmark
	Nitrobenzene	✓	
\checkmark	o-Cresol		
\checkmark	p-Cresol		
	Pentachlorophenol		
	Phenol	\checkmark	
		□ Heptachlor epoxide ✓ Lead □ Naphthalene □ Nitrobenzene ✓ o-Cresol ✓ p-Cresol □ Pentachlorophenol	Fluorene Image: Constraint of the system Heptachlor epoxide Image: Constraint of the system Naphthalene Image: Constraint of the system Nitrobenzene Image: Constraint of the system Image: Constraint of the system Image: Constraint of the system Image: Constraint of the system Image: Constraint of the system Image: Constraint of the system Image: Constraint of the system Image: Constraint of the system Image: Constraint of the system Image: Constraint of the system Image: Constraint of the system Image: Constraint of the system Image: Constraint of the system Image: Constraint of the system Image: Constraint of the system Image: Constraint of the system Image: Constraint of the system Image: Constraint of the system Image: Constraint of the system Image: Constraint of the system Image: Constraint of the system Image: Constraint of the system Image: Constraint of the system Image: Constraint of the system Image: Constraint of the system Image: Constraint of the system Image: Constraint of the system Image: Constraint of the system Image: Constraint of the system Image: Constraint of the system Image: Constraint of the system Image: Constraint of the system Image: Constraint of the system Imag

GEORGIA ENVIRONMENTAL PROTECTION DIVISION HAZARDOUS SITE INVENTORY

Site Number	10097
	10097

Pyrene	Selenium	
Styrene		
Xylenes	Zinc	