

Georgia Department of Natural Resources
Environmental Protection Division

Reply To:

Response and Remediation Program
2 Martin Luther King, Jr. Drive, S.E.
Suite 1054, East Tower
Atlanta, Georgia 30334-9000
Office 404/657-8600 Fax 404-657-0807

2 Martin Luther King, Jr. Dr., S.E., Suite 1456 East, Atlanta, Georgia 30334
Judson H. Turner, Director
Phone: (404) 656-4713 FAX: (404) 651-9425

September 12, 2014

Dickies Industrial Services, Inc.
c/o Ms. Joan Sasine, Esq.
Bryan Cave Powell, Goldstein
One Atlantic Center, Fourteenth Floor
1201 W. Peachtree Street, NW
Atlanta, Georgia 30309

VIA EMAIL & REGULAR MAIL

Re: Voluntary Remediation Program (VRP)
June 10, 2014, 3rd Annual Progress Report
Former Dickies Industrial Services, Inc., HSI #10127
Tax Parcels: 13-0036-LL-1349, -1414, -1463, and -1356
1411 Sullivan Road, College Park, Fulton County, GA

Dear Ms. Sasine:

The Georgia Environmental Protection Division (EPD) has received the June 10, 2014, Voluntary Remediation Program (VRP) 3rd Annual Progress Report (2014 Progress Report), which has been submitted by ERM on behalf of Dickies Industrial Services, Inc. pursuant to the Georgia Voluntary Remediation Program Act (the Act) O.C.G.A. 12-8-100. Based on EPD's review of this document, EPD has prepared the following comments:

- 1) According to the 2014 Progress Report, the detection limits for the groundwater analyses for monitoring locations MW-1 and MW-38A were well above routine laboratory detection limits due to dilution by the laboratory during preparation and analysis. These detection limits are orders of magnitude above the state promulgated groundwater and surface water criteria that will be used to evaluate the site during the groundwater modeling update that is to be completed at conclusion of the 5-year VRP monitoring period. Please ensure that additional efforts are made during future monitoring events to reduce the detection limit values at all monitoring locations to levels at or below the criteria that will be used during final groundwater modeling calculations.
- 2) Please include updated groundwater potentiometric maps as part of the Annual Progress Report submittals.

Should you have any question or concerns, please contact Mr. Kevin Collins of the Response and Remediation Program at (404) 463-0530.

Sincerely,



David Brownlee
Unit Coordinator
Response and Remediation Program

c: Amy Hickman, ERM
File: HSI #10127

S:\RDRIVE\KevinC\RRP Projects\VRP Applications\10127-Dickies Industrial Services\10127-VRP3rdProgressRptComments.docx