## **Part 70 Operating Permit Amendment**

Permit Amendment No.: 2421-107-0011-V-04-1 Effective Date: August 1, 2016

Facility Name: Interfor U.S. Inc. - Swainsboro Sawmill

Facility Address8796 GA Highway 297Swainsboro, Georgia 30401 (Emanuel County)

- Mailing Address:8796 GA Highway 297Swainsboro, Georgia 30401
- Parent/Holding International Forest Products Limited Company:

### Facility AIRS Number: 04-13-107-00011

In accordance with the provisions of the Georgia Air Quality Act, O.C.G.A. Section 12-9-1, et seq and the Georgia Rules for Air Quality Control, Chapter 391-3-1, adopted pursuant to and in effect under the Act, the Permittee described above is issued an amendment to the Part 70 Operating Permit for:

Increase production from existing direct-fired batch drying Kiln DK08 to 85 MMBF per year, add a powered stack to each end of existing direct-fired continuous drying kiln DK09 and to increase the sawmill capacity to 195 MMBF per year.

This Permit Amendment is conditioned upon compliance with all provisions of The Georgia Air Quality Act, O.C.G.A. Section 12-9-1, et seq, the Rules, Chapter 391-3-1, adopted and in effect under that Act, or any other condition of this Permit Amendment and Permit No. 2421-107-0011-V-04-0. Unless modified or revoked, this Permit Amendment expires simultaneously with Part 70 Permit No. 2421-107-0011-V-04-0.

This Permit Amendment may be subject to revocation, suspension, modification or amendment by the Director for cause including evidence of noncompliance with any of the above; or for any misrepresentation made in Application No. TV-40453 dated November 10, 2015, update of May 17, 2016; any other applications upon which this Permit Amendment or Permit No. 2421-107-0011-V-04-0 are based; supporting data entered therein or attached thereto; or any subsequent submittal or supporting data; or for any alterations affecting the emissions from this source.

This Permit Amendment is further subject to and conditioned upon the terms, conditions, limitations, standards, or schedules contained in or specified on the attached **7** pages.

[Signed]

Director Environmental Protection Division

### **Table of Contents**

<b>PART 1.0</b>	FACILITY DESCRIPTION	1
1.3	Process Description of Modification	1
<b>PART 3.0</b>	REQUIREMENTS FOR EMISSION UNITS	2
3.1.1	Revised Emission Units	2
3.2	Equipment Emission Caps and Operating Limits	2
3.4	Equipment SIP Rule Standards	3
3.5	Equipment Standards Not Covered by a Federal or SIP Rule and Not Instituted as an Emission Cap	р
	or Operating Limit	3
<b>PART 4.0</b>	REQUIREMENTS FOR TESTING	5
4.1	General Testing Requirements	5
<b>PART 6.0</b>	OTHER RECORD KEEPING AND REPORTING REQUIREMENTS	6
6.1	General Record Keeping and Reporting Requirements	6
6.2	Specific Record Keeping and Reporting Requirements	7

### PART 1.0 FACILITY DESCRIPTION

### **1.3** Process Description of Modification

The Permittee has decided to not convert lumber drying kiln DK08 to a continuous drying kiln (DK-10). The Permittee has requested a production increase for the batch drying kiln DK08 to 85 MMBF/year. The sawmills permitted production will also increase to 195 million BF/year. The facility will also add a powered stack to each end of the direct-fired continuous kiln DK09.

### PART 3.0 REQUIREMENTS FOR EMISSION UNITS

Note: Except where an applicable requirement specifically states otherwise, the averaging times of any of the Emissions Limitations or Standards included in this permit are tied to or based on the run time(s) specified for the applicable reference test method(s) or procedures required for demonstrating compliance.

### **3.1.1 Revised Emission Units**

Emission Units		Specific Limitations/Requirements		Air Pollution Control Devices	
ID No.	Description	Applicable Requirements/Standards	Corresponding Permit Conditions	ID No.	Description
DK08	Existing lumber drying kiln	40 CFR 63 Subpart A	3.2.1, 3.3.1, 3.4.1, 3.4.2,	N/A	None
	(batch), direct heated by	40 CFR 63 Subpart DDDD	3.4.3, 6.1.7, 6.2.1, 6.2.2,		
	green sawdust fired gasifier	391-3-102(2)(b)	6.2.3, 6.2.4, 6.2.5, 7.14.1,		
	(85 MMBF/year capacity)	391-3-102(2)(e)	7.14.2		
		391-3-102(2)(g)			
DK09	Continuous type lumber	40 CFR 63 Subpart A	3.2.1, 3.2.2, 3.3.1, 3.4.1,	N/A	None
	drying kiln, direct heated	40 CFR 63 Subpart DDDD	3.4.2, 3.4.3, 6.1.7, 6.2.1,		
	by green sawdust fired	391-3-102(2)(b)	6.2.2, 6.2.3, 6.2.4		
	gasifier	391-3-102(2)(e)			
	(110 MMBF/yr capacity)	391-3-102(2)(g)			
DK10	Proposed Continuous type	40 CFR 63 Subpart A	<del>3.2.1, 3.2.2, 3.3.1, 3.4.1,</del>	N/A	None
	lumber drying kiln, direct	40 CFR 63 Subpart DDDD	<del>3.4.2, 3.4.3, 6.1.7, 6.2.1,</del>		
	heated by green sawdust	<del>391-3-102(2)(b)</del>	<del>6.2.2, 6.2.3, 6.2.4, 6.2.5</del>		
	fired gasifier	<del>391-3-102(2)(e)</del>			
	(110MMBF/yr capacity)	<del>391-3-102(2)(g)</del>			
PM01	Planer Mill	391-3-102(2)(b)	3.4.1, 3.4.2, 3.5.1, 3.5.2,	PMC1	Planer Mill Baghouse
		391-3-102(2)(e)	5.2.1, 5.2.2, 5.2.3, 5.2.4,		
			6.1.7, 6.2.4		

\* Generally applicable requirements contained in this permit may also apply to emission units listed above. The lists of applicable requirements/standards and corresponding permit conditions are intended as a compliance tool and may not be definitive.

### 3.2 Equipment Emission Caps and Operating Limits

### Amended Condition

- 3.2.1 The Permittee shall not dry more than the following specified board feet of lumber per any twelve consecutive months in the lumber drying kilns, under the indicated scenarios. [PSD/BACT, 40 CFR 52.21 and 391-3-1-.03(2)(c)]
  - a. The Permittee shall not dry more than 195 million board feet total from both drying kilns DK08 and DK09 or more than 85 million board feet in drying kiln DK08 per any twelve consecutive months.
- 3.2.2 Condition deleted.

### **3.4 Equipment SIP Rule Standards**

### Amended Condition

- 3.4.1 The Permittee shall not cause, let, suffer, permit, or allow the emission from each lumber drying kilns DK08 and DK09 or the planer mill PM01, any gases which contain particulate matter equal to or exceeding the allowable rate as calculated using the applicable equation below, unless otherwise specified in this Permit. [391-3-1-.02(2)(e)]
  - a.  $E = 4.1P^{0.67}$  for process input weight rate up to and including 30 tons per hour;
  - b.  $E = 55P^{0.11} 40$  for process input weight rate in excess of 30 tons per hour.

### Where:

E = allowable PM emission rate in pounds per hour;

P = process input weight rate in tons per hour.

3.4.2 The Permittee shall not cause, let, suffer, permit or allow emissions from any lumber drying kilns DK08 and DK09 or the planer mill baghouse PMC1, the opacity of which is equal to or greater than forty percent. [391-3-1-.02(2)(b)1]

# **3.5** Equipment Standards Not Covered by a Federal or SIP Rule and Not Instituted as an Emission Cap or Operating Limit

### New Condition

3.5.3 The Permittee shall develop and implement a Work Practice and Preventive Maintenance Program for the lumber drying kilns (D08 and DK09) within 120 days from the issuance of this permit. The program shall be subject to review and modification by the Division. At a minimum, the following operational and maintenance checks shall be made and a record of the findings and corrective actions taken, shall be kept in electronic or manual maintenance logs:

[391-3-1-.02(6)(b)1, 40 CFR 52.21, and 40 CFR 70.6(a)(3)(i)]

- a. General Work Practice Standards for Wood-Drying Kiln Operation:
  - i. The lumber kiln drying operation target final moisture content will be 12% or greater based on a 12-month rolling average. Moisture content will be measured with a moisture meter at the outfeed of the planer mill.
  - ii. Routines for periodic preventative maintenance are detailed in paragraphs b, c, d and e of this condition. With future equipment changes or modifications, these preventative maintenance activities can be modified pending approval from EPD.

- b. Daily Routine:
  - i. Make certain all fans are running properly. If one "trips out" frequently or becomes inoperable, investigate to determine the reason and then document the corrective actions.
  - ii. Check to verify that the kiln heating system (direct-fired gasifier) is operating properly.
- c. Quarterly Routine:
  - i. Grease fan motors, shafts and bearings and inspect fan blades for damage. Check fan clearances, rotation, tension and replace belts if required.
  - ii. Inspect kiln walls, doors and baffles for deterioration and schedule repairs as needed.
  - iii. Inspect temperature monitoring systems for proper operation.
  - iv. Inspect vents and linkages (batch kiln DK08). Schedule repairs as needed.
  - v. If necessary sweep out kiln to remove accumulated dust (batch kiln DK08).
  - vi Inspect and repair as necessary external components of direct-fired gasifier of continuous kiln DK09 and batch kiln DK08.
- d. Semi-annual Routine:
  - i. Verify accuracy of the temperature measurement systems. Repair or replace components as necessary.
  - ii. During cold shutdown of continuous kiln DK09, inspect and repair as necessary all internal components of kilns and direct-fired gasifiers. During this time the continuous kiln DK09 and burner should be thoroughly cleaned of accumulated dust.
- e. Any adverse condition discovered by this inspection shall be corrected in the most expedient manner possible. The Permittee shall record problems discovered in a maintenance log/checklist or the plant's Computerized Maintenance Management System (CMMS), indicating the corrective action(s) taken, and date of the required maintenance completion. If a problem during inspection cannot be remedied within 48 hours of discovery and if the problem does not result in excess emissions, it shall be entered into the plant's Computerized Maintenance Management System (CMMS) as equipment downtime.

### PART 4.0 REQUIREMENTS FOR TESTING

### 4.1 General Testing Requirements

#### Amended Condition

- 4.1.3 Performance and compliance tests shall be conducted and data reduced in accordance with applicable procedures and methods specified in the Division's Procedures for Testing and Monitoring Sources of Air Pollutants. The methods for the determination of compliance with emission limits listed under Sections 3.2, 3.3, 3.4 and 3.5 are as follows:
  - a. Method 1 for the determination of sample point locations.
  - b. Method 2 for the determination of stack velocity and volumetric flow rate.
  - c. Method 3 or 3A for the determination of stack gas molecular weight.
  - d. Method 3B for the determination of the emission rate correction factor or excess air.
  - e. Method 4 for the determination of stack gas moisture content.
  - f. Method 5 in conjunction with Method 202 for the determination of Total Particulate Matter concentration (filterable + condensible).
  - g. Method 9 and the procedures contained in Section 1.3 of the above reference document for the determination of opacity.
  - h. ASTM D129, D2622 or D4294 for the determination of fuel sulfur content.
  - i. The procedures of the NCASI Wood Products Protocol 1 shall be used to determine the VOC concentration from the continuous drying kiln DK09.

Minor changes in methodology may be specified or approved by the Director or his designee when necessitated by process variables, changes in facility design, or improvement or corrections that, in his opinion, render those methods or procedures, or portions thereof, more reliable. [391-3-1-.02(3)(a)]

### PART 6.0 OTHER RECORD KEEPING AND REPORTING REQUIREMENTS

### 6.1 General Record Keeping and Reporting Requirements

### Amended Condition

- 6.1.7 For the purpose of reporting excess emissions, exceedances or excursions in the report required in Condition 6.1.4, the following excess emissions, exceedances, and excursions shall be reported:
  [391-3-1-.02(6)(b)1 and 40 CFR 70.6(a)(3)(i)]
  - a. Excess emissions: (means for the purpose of this Condition and Condition 6.1.4, any condition that is detected by monitoring or record keeping which is specifically defined, or stated to be, excess emissions by an applicable requirement)

None required to be reported in accordance with Condition 6.1.4.

- b. Exceedances: (means for the purpose of this Condition and Condition 6.1.4, any condition that is detected by monitoring or record keeping that provides data in terms of an emission limitation or standard and that indicates that emissions (or opacity) do not meet the applicable emission limitation or standard consistent with the averaging period specified for averaging the results of the monitoring)
  - i. Any twelve consecutive month period during which more than 195 million board feet of lumber are dried in the lumber drying kilns DK08 and DK09 and/or more than 85 million board feet in drying kiln DK08.
  - ii. Deleted.
- c. Excursions: (means for the purpose of this Condition and Condition 6.1.4, any departure from an indicator range or value established for monitoring consistent with any averaging period specified for averaging the results of the monitoring)
  - i. Any adverse condition(s) discovered by the weekly inspections, as required in Condition No. 5.2.2, of the planer mill shaving system cyclone and baghouse PMC1.
  - ii. Any two consecutive required daily determinations of visible emissions from the same source requiring action by Condition 5.2.3.

### 6.2 Specific Record Keeping and Reporting Requirements

### Amended Condition

- 6.2.2 The Permittee shall notify the Division in writing if the amount of dried lumber processed through all drying kilns exceeds the following specified limits. This notification shall be postmarked by the fifteenth day of the following month and shall include an explanation of how the Permittee intends to maintain compliance with the limit in Condition No. 3.2.1. [391-3-1-.02(6)(b)1 and 40 CFR 70.6(a)(3)(i)]
  - a. 16.25 MMBF, during any calendar month, through drying kilns DK08 and DK09 combined or 7.08 MMBF during any calendar month, through drying kiln DK08.
  - b. condition deleted.
- 6.2.5 Condition deleted.