Section 2.107 Rev. (1) 9/89 Page 1 of 2

2.107 Metallic Mineral Processing Plants

- 2.107.1 Applicability and Designation of Affected Facility
 - (a) The provisions of this source category are applicable to the following affected facilities in metallic mineral processing plants: Each crusher and screen in open-pit mines; each crusher, screen, bucket elevator, conveyor belt transfer point, thermal dryer, product packaging station, storage bin, enclosed storage area, truck loading station, truck unloading station, railcar loading station, and railcar unloading station at the mill or concentrator with the following exceptions. All facilities located in underground mines are exempted from the provisions of this source category. At uranium ore processing plants, all facilities subsequent to and including the beneficiation of uranium ore are exempted from the provisions of this source category.

2.107.2 Test Methods and Procedures

- (a) In conducting the performance tests required in Section 1.2, the owner or operator shall use as reference methods and procedures the test methods in Appendix A of this part or other methods and procedures as specified in this section, except as provided in Section 1.2(b).
- (b) The owner or operator shall determine compliance with the particulate matter standards as follows:
 - (1) Method 5 or 17 shall be used to determine the particulate matter concentration. The sample volume for each run shall be at least 1.70 dscm (60 dscf). The sampling probe and filter holder of Method 5 may be operated without heaters if the gas stream being sampled is at ambient temperature. For gas streams above ambient temperature, the Method 5 sampling train shall be operated with a probe and filter temperature slightly above the effluent temperature (up to a maximum filter temperature of 121°C (250°F) in order to prevent water condensation on the filter.
 - (2) Method 9 and the procedures in Section 1.3 shall be used to determine opacity from stack emissions and process fugitive emissions. The observer shall read opacity only when emissions are clearly identified as emanating solely from the affected facility being observed.
- (c) To comply with \$2.107.3(c), the owner or operator shall use the monitoring devices in \$2.109.4(a) and (b) to determine the pressure loss of the gas stream through the scrubber and scrubbing liquid flow rate at any time during each particulate matter run, and the average of the three determinations shall be computed.

2.107.3 Recordkeeping and Reporting Requirements

- (a) The owner or operator subject to the provisions of this source category shall conduct a performance test and submit to the Director a written report of the results of the test as specified in Section 1.2.
- (b) During the initial performance test of a wet scrubber, and at least weekly thereafter, the owner or operator shall record the measurements of both the change in pressure of the gas stream across the scrubber and the scrubbing liquid flow rate.
- (c) After the initial performance test of a wet scrubber, the owner or operator shall submit semiannual reports to the Director of occurrences when the measurements of the scrubber pressure loss (or gain) and liquid flow rate differ by more than ±30 percent from those

measurements recorded during the most recent performance test.

- (d) The reports required under paragraph (c) shall be postmarked within 30 days following the end of the second and fourth calendar guarters.
- 2.107.4 Emission and Operation Monitoring
 - (a) The owner or operator subject to the provisions of this source category shall install, calibrate, maintain, and operate a monitoring device for the continuous measurement of the change in pressure of the gas stream through the scrubber for any affected facility using a wet scrubbing emission control device. The monitoring device must be certified by the manufacturer to be accurate within ±250 pascals (±1 inch water) gauge pressure and must be calibrated on an annual basis in accordance with manufacturer's instructions.
 - (b) The owner or operator subject to the provisions of this source category shall install, calibrate, maintain, and operate a monitoring device for the continuous measurement of the scrubbing liquid flow rate to a wet scrubber for any affected facility using any type of wet scrubbing emission control device. The monitoring device must be certified by the manufacturer to be accurate within ±5 percent of design scrubbing liquid flow rate and must be calibrated on at least an annual basis in accordance with manufacturer's instructions.