



TYPICAL EMBANKMENT DAM
 (COMMON DEFICIENCIES NOTED IN ORANGE)

REF: MODIFIED FROM TADS, U.S. BUREAU OF RECLAMATION; 1988.