

3.1 Asbestos

3.1.1 Test Methods and Procedures

Reference Method 9 in Appendix A of this text shall be used to determine compliance with applicable visible emission standards.