



September 30, 2015

Ms. Robin Futch
Georgia Department of Natural Resources
Response and Remediation Program
2 Martin Luther King, Jr. Drive
S.E. Suite 1462, East Tower
Atlanta, Georgia 30334-9000

RE: Voluntary Remediation Program
Semi-Annual Status Report No. 6
Supplemental Draft Isoconcentration Maps
Tara Shopping Center
8564 Tara Boulevard, Jonesboro, Clayton County, Georgia
Tax Parcel ID 13242D B001; HSI Site No. 10798

Dear Ms. Futch,

Please find attached two (2) copies of the draft isoconcentration maps prepared for the Tara Shopping Center located at 8564 Tara Boulevard, Jonesboro, Clayton County, Georgia. These maps represent the groundwater conditions as of July 2015 and supplement the previously submitted Semi-Annual Progress Report, dated August 28, 2015. Isoconcentration maps were created for the primary constituents of concern related to the former dry cleaner site and include tetrachloroethene, trichloroethene, cis-1,2-dichloroethene, and vinyl chloride. Isoconcentration contours are drawn to the maximum contaminant level for each constituent within the shallow and deep residuum, and bedrock water bearing zone. To assist in the nature and extent evaluation, groundwater potentiometric surface contours are represented on each figure.

If you should have any questions regarding the information presented, please contact me at michelle.stayrook@ehs-support.com or 412-807-1494.

Sincerely,

Michelle Stayrook
EHS Support
Project Manager

Attachments

cc: Michael Dever, Ashland (email)
Kristin VanLandingham, P.E. EHS Support (email)













