

**GEORGIA ENVIRONMENTAL PROTECTION DIVISION
HAZARDOUS SITE INVENTORY**

Site Number: **10385**


SITE NAME: Baldwin County Sanitary Landfill
LOCATION: 170 Union Hill Church Road
 Milledgeville, Baldwin County, GA 31061

Latitude 32° 57' 55" N Longitude 83° 19' 59" W

ACREAGE **PARCEL NUMBER** **DATE LISTED**
 533.84 011 003 8/4/1995

LAST KNOWN PROPERTY OWNER:

Baldwin County Board of Commissioners
 201 West Hancock Street
 Milledgeville, GA 31061



STATUS OF CLEANUP ACTIVITIES:

Cleanup activities are being conducted for source materials and groundwater.

CLEANUP PRIORITY: The Director has designated this site as a Class IV

GA EPD DIRECTOR'S DETERMINATION REGARDING CORRECTIVE ACTION:

The Director has determined that this site requires corrective action.

REGULATED SUBSTANCES RELEASED, AND THREATS TO HUMAN HEALTH AND ENVIRONMENT POSED BY THE RELEASE:

This site has a known release of Vinyl chloride in groundwater at levels exceeding the reportable quantity. No human exposure via drinking water is suspected from this release. The nearest drinking water well is less than 0.5 miles from the area affected by the release.

REGULATED SUBSTANCES:

| Substance Name | GW | Soil | Substance Name | GW | Soil |
|----------------|-------------------------------------|--------------------------|----------------|-------------------------------------|--------------------------|
| Arsenic | <input checked="" type="checkbox"/> | <input type="checkbox"/> | Barium | <input checked="" type="checkbox"/> | <input type="checkbox"/> |
| Mercury | <input checked="" type="checkbox"/> | <input type="checkbox"/> | Vinyl chloride | <input checked="" type="checkbox"/> | <input type="checkbox"/> |
| Zinc | <input checked="" type="checkbox"/> | <input type="checkbox"/> | | | |