SITE NAME: Baxley Creosoting Company

LOCATION: 723 East Parker Street

Baxley, Appling County, GA 31513

Latitude 31° 46' 29" N Longitude 82° 20' 11" W

ACREAGE PARCEL NUMBER


DATE LISTED

10.63 S002 035

6/29/1994

LAST KNOWN PROPERTY OWNER:

Baxley Creosoting Company 581 East Parker Street Baxley, GA 31513



STATUS OF CLEANUP ACTIVITIES:

Hazardous Site Response Act cleanup levels have been met for source materials and soil. Identified responsible parties are unable or unwilling to conduct the required investigation and/or cleanup under the Hazardous Site Response Act for groundwater. EPD may perform these actions using state funding from the Hazardous Waste Trust Fund and may lien the property or pursue cost recovery.

CLEANUP PRIORITY: The Director has designated this site as a Class I

GA EPD DIRECTOR'S DETERMINATION REGARDING CORRECTIVE ACTION:

The Director has determined that this site requires corrective action.

REGULATED SUBSTANCES RELEASED, AND THREATS TO HUMAN HEALTH AND ENVIRONMENT POSED BY THE RELEASE:

This site has a known release of Benzo(a)pyrene in soil at levels exceeding the reportable quantity. This site has unlimited access. The nearest resident individual is between 301 and 1000 feet from the area affected by the release.

REGULATED SUBSTANCES:

Substance Name	GW Soil	Substance Name	GW Soil
2,3,4,6-Tetrachlorophenol		2,4,6-Trichlorophenol	
Acenaphthene	✓	Anthracene	
Arsenic		Benzo(a)anthracene	
Benzo(a)pyrene		Benzo(b)fluoranthene	
Benzo(k)fluoranthene		Chromium	
Chrysene		Creosote	
Dibenzo(a,h)anthracene		Fluoranthene	
Indeno(1,2,3-cd)pyrene		Naphthalene	
Pentachlorophenol		Phenol	
Pyrene			