Georgia Environmental Protection Division - Underground Storage Tank (UST) Management Program

Public Record Report for FFY 2016

General Information

Total Number of UST Facilities: 9,705
Total Number of USTs: 29,116

Public Record Posted Date: December 22, 2016

Summary Information for Inspections

Number of UST Facilities Inspected: 3,360

Inspection Period Dates Were From: To: 10/01/2015 - 09/30/2016

Percent Compliance (Combined Measure): 66%

Note: Tank, facility, and on-site inspection information is based on underground storage tanks regulated under Subtitle I that satisfy the definition of UST in 40 CFR 280.12, except for those tanks identified in 40 CFR 280.10(b) as excluded USTs and those deferred in 40 CFR 280.10(c). Inspections measure compliance with EPA SOC for the combined measures of Release Prevention and Release Detection.

Summary Information for Releases

Number of Confirmed UST Releases: 266

Release Period Dates Were From: To: 10/01/2015 - 09/30/2016

Summary Information for Release Sources and Causes

Source		Cause														
Source			Spill		Overfill		Phys/Mech		Corrosion		Install		Other		Unknown	
	#	%	#	%	#	%	#	%	#	%	#	%	#	%	#	%
Tank	9	3%	0	0%	0	0%	1	11%	1	11%	0	0%	0	0%	7	78%
Piping	10	4%	0	0%	0	0%	1	10%	2	20%	0	0%	0	0%	7	70%
Dispenser	1	0%	0	0%	0	0%	0	0%	0	0%	0	0%	0	0%	1	100%
Submerged																
Turbine	0	0%	0	0%	0	0%	0	0%	0	0%	0	0%	0	0%	0	0%
Pump																
Delivery	2	1%	0	0%	0	0%	0	0%	0	0%	0	0%	0	0%	2	100%
Problem																
Other	3	1%	0	0%	0	0%	1	33%	0	0%	0	0%	0	0%	2	67%
Unknown	241	91%	0	0%	0	0%	3	1%	0	0%	1	0%	0	0%	237	98%
Totals	266		0		0		6		3		1		0		256	

= number, % = percent of total number

Note: Release, source, and cause information is based on underground storage tanks regulated under Subtitle I that satisfy the definition of UST in 40 CFR 280.12, except for those USTs indentified in 40 CFR 280.10(b). UST's deferred in 40 CFR 280.10(c) and those used for emergency power generation (deferred from release detection by 40 CFR 280.10(d)) are included as part of the public record.

This report reflects data from releases reported to EPD during the time period of the report. Source and cause data were collected using on-site inspections and reports from facilities. The locations of these releases were not identifiable. "OTHER" is an identifiable source that does not fit specific locations identified in the chart.