

Georgia Department of Natural Resources
Environmental Protection Division

2 Martin Luther King, Jr. Dr., Suite 1456, Atlanta, Georgia 30334-9000
Judson H. Turner, Director
Phone (404) 656-4713

June 26, 2014

COPY

Mr. Mitchell Wirth
F.S. Associates, L.P.
c/o Mr. Scott Laseter
Kazmarek Mowrey Cloud Laseter LLP
1230 Peachtree Street, N.E., Suite 3600
Atlanta, GA 30309

Re: 1st Annual Groundwater Monitoring Report
Hunting Creek Shopping Plaza, HSI Site No. 10832
Conyers, Rockdale County, Georgia
Tax Parcel ID: 075001034A

Dear Mr. Wirth:

The Georgia Environmental Protection Division (EPD) has reviewed the January 15, 2014, 1st Annual Groundwater Monitoring Report, submitted by AMEC, pursuant to the Georgia Voluntary Remediation Program Act (the Act). Our comments are as follows:

1. The report states the monitoring wells were purged with a peristaltic pump but does not discuss the procedure used to collect the groundwater samples, or if the tubing was teflon. The method used to sample the wells (i.e. straw method) should be described in the next monitoring report.
2. EPD recommends that for the multiple purge volume method, the pump intake be placed at the top of the water column during purging of shallow wells rather than at the screen midpoint.

The above comments should be addressed in the next progress report. If you have any questions, please contact Bill Williams of the Response and Remediation Program at (404) 657-8600.

Sincerely,



David Reuland
Unit Coordinator
Response and Remediation Program

cc: Charles T. Ferry, AMEC